

Welland Soccer Club Buffer Planting



Before Restoration

The Welland Soccer Club is a publicly used park which receives a lot of foot traffic. Before restoration, the bank of the creek was barren of vegetation and provided no wildlife habitat or water quality protection.

Planting was undertaken along a 10 m stretch of the creek here, with the help of over 20 community volunteers. The project has established over 1000 m² of riparian habitat!



After Restoration